



SENTOSA TEKNIK AC

PRICE LIST

SERVICE CLEANING AC

Service Ac split 0,5 - 1 PK	80k
Service Ac split 1,5 - 2,5 PK	95k
Service Ac Standing floor	250k
Service Ac cassette	250k
Cuci Besar Ac 0,5 - 1 PK	150k
Cuci Besar Ac 1,5 - 2 PK	200k

BONGKAR & PASANG AC

pasang ac 0,5 - 1 pk + vakum	250k
bongkar ac 0,5 - 1 pk	150k
Bongkar pasang ac 0,5 - 1 pk	350k
Pasang Ac 1,5 - 2 pk + vakum	300k
Bongkar ac 1,5 - 2 pk	200k
Bongkar pasang 1,5 - 2 pk	400k

SPEARPART AC

Kapasitor Compresor	185k
Overload	135k
Termistor indoor	150k
Modul / PCB	350k
Motor blower outdoor & indoor	425k
Motor swing indoor	150k
pengelasan pipa ac	75k
steker ac kaki 3 set	130k

PENAMBAHAN FREON AC

penambahan freon 0,5 - 1 PK	220k
Penambahan freon 1,5 - 2,5 PK	320k
Pengisian Full freon 0,5 - 1 PK	350k
Pengisian Full freon 1,5 - 2,5 PK	450k

Tipe freon ac R32, R22, R410

MATERIAL AC

pipa ac 0,5 - 1 PK per m	125k
pipa ac 1,5 - 2 PK per m	150k
breket outdoor 0,5 - 1 PK	80k
breket outdoor 1,5 - 2 PK	90k
kabel listrik 3 x 1,5 per m	25k
Drain air per m	5k

LAIN LAIN

overhoul indoor	300k
overhoul outdoor	750k
Ganti Compresor	
Tukar tambah Ac	
Jual beli ac	